


C9 Runner

Sample of
Runner Hub
Cavitation Areas
needing Repair





C9 Cavitation Damage on Hub



FWO/CO 2-10 Repair



Repaired
Cavitation Area:
Excavate to
sound metal,
309L weld
overlay, final
machining to be
performed.

Conic Cover

