
## RR Generating Units

(Updated January 2020)

Year = date scheduled to return to service



Out of Service, awaiting trunnion bushing replacement,

Note: evaluating whether we can hydraulically block blades on C3 and operate in interim

In Service, with trunnion bushing replacement scheduled in 2020-2022

Out of service.

Large unit
being repaired

In service. Large unit repair complete

In Service with blade blocks, repair scheduled 2021-2023

