


Rock Island Fishway Drop Gate Structure



Drop Gate
Structure

Powerhouse #1

Structural Analysis identified vulnerability in the Rock Island Fishway Drop Gate Structure. No impact to daily operations. Recommendation is to mitigate risk from moderate seismic event or extreme water surface elevation. Not an imminent threat, but repairs recommended.

